Serial Number: 10/709,364 Filed: 4/29/2004

Remarks

The Examiner rejected claims 18-21 under 35 U.S.C. 102(b) as anticipated by Haller. As

suggested by the Examiner in his "Response to Arguments" (6/19/06 OA, p. 10), the first spring of

Haller does not directly or electrically contact the inner diameter surface. Claim 18 has been

amended to clarify that the first spring is biased to directly contact the inner diameter surface.

The male portion of Haller has a second outer contact 41 sleeve (identified by the Examiner as

the "first spring") formed in a "c" shape that presses axially against the forward end of a female

portion helical spring "second contact 16", compressing the spring axially to form a secure contact

as the connector portions are mated together (col. 2 In 42-52). The lower ends 50, 51 of the

second outer contact 41 sleeve mate within axial slits 78 of the first body for radial support,

preventing radial deformation of the second outer contact 41 to ensure it presses axially against

the forward end of the second contact 16, even if the connector bodies are rotated with respect to

each other (col. 4 In 4-22).

As specifically cited from the Haller description, herein above, the Haller "first spring" only

contacts the second contact 16, axially, not the inner diameter surface. The "first spring" is

insulated from the inner diameter surface by passage through the axial slits 78 of the housing 36

(see Haller, figures 7 and 9). Because the "first spring" identified by the Examiner in Haller does

not directly contact the inner diameter surface, whatsoever, each and every element of the

claimed invention fails to appear in the cited reference. Therefore, rejection of claims 18-21

under 35 USC 102(b) is improper.

The Examiner rejected claims 1-4, 9-10 and 12-17 under 35 USC 103(a) as unpatentable over

Guimond in view of Nelson. The Guimond connector is an extremely complex cam action device

with a plurality of separate components, each of which decreases the reliability and increases the

required number of manufacturing steps and overall cost of the resulting connector. Guimond

Page 6 of 9

Serial Number: 10/709,364

Filed:

4/29/2004

the pivoting spring fingers created by the spring 50.

has a body 18 to which a plurality of fingers 30, cited as outer "spring fingers" by the Examiner, are movably attached by pins 62. The fingers 30 are biased in an open position (col. 3, line 35), by a mechanical cam interaction with an axially slidable coaxial line segment 14 biased into a forward axial position by a spring 50 that holds the fingers 30 in the open position by cam action. The outer "spring fingers" are not biased for an interference fit with the outer diameter surface, they only contact the outer diameter surface upon removal of the mechanical cam action via axial movement of the coaxial line segment 14 and sleeve 35 to overcome the open position bias of

Further, independent claim 1 has been amended to clarify that the outer spring fingers according to the invention are integral with the body (see specification figures 5 and 11), not the separate elements movably attached to the body as appear in *Guimond*. No spring fingers of any kind appear in *Nelson*.

Because the *Guimond* outer "spring fingers" are neither biased for an interference fit with the outer diameter surface nor integral with the body as claimed by the present invention, each and every element of the invention fails to be disclosed, taught or suggested by the cited references. Therefore, rejection of claims 1-4, 9-10 and 12-17 under 35 USC 103(a) is improper.

The Examiner rejected claims 5-8 and 26-29 under 35 USC 103(a) as unpatentable over *Guimond* in view of *Nelson* and further in view of *Plummer*. The Examiner supplies *Plummer* to demonstrate a first spring having an interference fit collar with outward projecting spring fingers. Therefore, with respect to claims 5-8, the addition of *Plummer* still fails disclose, teach or suggest spring fingers biased for an interference fit with the outer diameter surface, the spring fingers integral with the body as described in detail herein above. Therefore, rejection of claims 5-8 under 35 USC 103(a) is improper.

Serial Number: 10/709,364

Filed:

4/29/2004

Claims 26-29 have been canceled.

The Examiner rejected claims 22 and 24-25 under 35 USC 103(a) as unpatentable over *Haller* in view of *Maury* and further in view of *Plummer*. The Examiner states that *Haller* discloses the claimed invention except for a second spring located in a second groove located around the plurality of outer spring fingers, the second spring biasing the spring fingers inward, and supplies *Maury* therefore. The fact that *Haller* fails to disclose each and every element of independent claim 18, as currently amended, from which claims 22 and 24-25 depend is addressed in detail herein above.

Further, the outer spring fingers the Examiner has identified in *Maury* are not biased inward, they are biased outward and the second spring identified by the Examiner is in fact itself an electrical contact, not a bias element as the outer diameter mounting position of the "second spring" around the "outer spring fingers" cited by the Examiner would inhibit rather than enhance the spring fingers outward bias (col. 2 In 34-53). Because the Examiner has failed to identify each and every element of the invention as disclosed, taught or suggested in the cited references, rejection of claims 22 and 24-25 under 35 USC 103(a) is improper.

The Examiner rejected claim 11 under 35 USC 103(a) as unpatentable over *Guimond* in view of *Nelson* and further in view of *Maury*. The Examiner states that *Guimond* in view of *Nelson* discloses the claimed invention except for the connector having an SMA or Type N connector interface and supplies *Maury* therefore. As described in detail herein above with respect to independent claim 1, as currently amended, from which claim 11 depends, *Guimond* and or *Nelson* both fail to demonstrate the claim elements of outer spring fingers biased for an interference fit with the outer diameter surface or the outer spring fingers integral with the body as claimed by the present invention. Further, the Examiner's description of *Maury* similarly fails to identify these elements. Therefore, rejection of claim 11 under 35 USC 103(a) is improper.

Serial Number: 10/709,364

Filed:

4/29/2004

The Examiner rejected claim 23 under 35 USC 103(a) as unpatentable over Haller. The

Examiner states that Haller discloses the claimed invention except for a third groove for the first

spring on the inner diameter surface of the bore. The fact that Haller fails to disclose each and

every element of independent claim 18, as currently amended, from which claim 23 depends is

addressed in detail herein above. Therefore, rejection of claim 23 under 35 USC 103(a) is

improper.

Having obviated each of the Examiners rejections, applicant respectfully requests that a notice of

allowance be issued. Should the Examiner be inclined to issue an Official Action other than the

notice of allowance, Applicant respectfully requests that the Examiner first contact Applicant by

telephone at the number listed below.

Respectfully submitted,

Andrew Babcock, Esq. Attorney for Applicant

Registration Number 44517

Babcock IP, LLC 24154 Lakeside Dr.

Lake Zurich, IL 60047

Telephone: 847 719-2063

Fax: 847 438-5743